



Materials Recovery Facility
Safety Observation Form

Date: Friday, June 24, 2016


Name of Observer: Ron Kovaleski

Issues: See below.

Photos:



All: Dust, dirt, debris atop electrical panels



Top left: wiring hanging from ceiling, no caps.

Top right: wiring hanging from ceiling w/ cardboard hanging from wiring

Middle: wiring strung over stairwell and under machinery

Bottom: Wiring hanging over stairway, covered with dirt & debris





Top left: wiring under conveyer with debris over/under/on/around wire

Top right: stairwell blocked, covered with debris

Center: wiring with debris around wire

Bottom left: wiring with debris hanging from it

Bottom right: wiring underneath conveyer with debris hanging





Top left: dust & debris atop electric motor

Top right: dust & debris atop light fixture

Center: dust & debris atop electric motor

Bottom: uneven flooring – trip hazard

