



Materials Recovery Facility  
Safety Observation Form

Date: Saturday, June 25, 2016

Name of Observer: Shawn Qualls

Issues: See below.

Photos:



Left:

- Exposed wiring
- Labels deteriorating. Looks like '160 volts,' actually 460 volts.



All: Ladder safety

- Ladder is backwards
- Unstable [1910.26(c)(3)(iii)]
- Angle too steep (1:4 rule not adhered to) [1910.26(c)(3)(i)]
- Not secured at top
- Warnings/labels illegible
- Damage to frame and rungs [1910.26(c)(2)(vii)]
- Not inspected prior to use