

## Materials Recovery Facility Safety Observation Form


Name of Observer: Shawn Qualls Date: Tuesday, July 5th, 2016

Issues: See below.

## Photos:



Machine not locked out. (May fall under minor service exception? [1910.147(a)(2)(ii)])









Lots of uncapped wires, potential shock hazard. (work in progress)







Top left: Possible clearance issue.

Top right: Fire extinguisher still missing

Bottom: Replace missing eye wash bottle










All: Housekeeping – obstructed walkways and stairways [1910.22(a)(1)] Bottom left: possible clearance issue?







Bottom: PPE left lying around






Top left: Looks like the upper motor is missing a guard

Top right: Center motor – guard (top) is not secured to motor.

Bottom left: Panel not secured

Bottom right: Damaged guard

6 MRF INSPECTION - 07/05/2016



Conveyor overloaded