

CITY OF ANN ARBOR MRF INSPECTIONS

Findings From June 12, 2016

(Steven Schantz, Jose (Shift Supervisor))

The following findings were identified during a safety inspection at the MRF on June 12, 2016.

Missing sprinkler cover ring (noted on previous inspections)



Improperly stored and labeled chemicals / liquids.



Improperly stored chemicals located at the Transfer Station




ISSUES CORRECTED FROM PREVIOUS INSPECTIONS

Corrected confined space security



Corrected blockage of baler E-stop



Corrected machine damage



Corrected material build-up on conveyer roller

