



Materials Recovery Facility
Safety Observation Form

Date: Wednesday, July 6th, 2016


Name of Observer: Shawn Qualls

Issues: See below.

Photos:



CG cylinders stored less than 20 feet
from flammables/combustible
materials (NFPA 51 2-2.1, 2-4.1)



Top left: Ladder storage

- Improper storage
- Ladder looks as though it may have been set up for use as a platform. Did not witness anyone using it as such, but 1910.26(c)(3)(vii) prohibits the use of ladders as platforms, gangways, etc.

Top right: Fire extinguisher in red rental forklift has no inspection details. Zip tie around the neck suggests there was a tag there at one point, but it has since fallen off. Also, the label is peeling away near where the serial number is located.

Bottom: Dumpster parked against (newly replaced) steel support beams. Dumpster door is also pinned shut.



New wall presents possible clearance issue. 20 CFR 1910.303(g)(1)(i)(B) states:
“The width of working space in front of the electric equipment shall be the width of the equipment or 762 mm (30 in.), whichever is greater. In all cases, the working space shall permit at least a 90-degree opening of equipment doors or hinged panels”