STATE OF MICHIGAN IN THE CIRCUIT COURT FOR THE COUNTY OF WASHTENAW

CAN IV PACKARD SQUARE, LLC, a Delaware limited liability company,

Plaintiff,

Case No. 16-990-CB Hon. Archie C. Brown

V

PACKARD SQUARE, LLC, A Michigan limited liability company,

Defendant,

RECEIVER'S NOTICE OF FILING OF RECEIVER'S REPORT DATED AUGUST 25, 2017

and

ALLIED BUILDING PRODUCTS CORP., an Ohio corporation, AMTHOR STEEL, a Pennsylvania corporation, ASSEMBLERS PRECAST & STEEL SERVICES, INC., a Michigan corporation, THE BELDEN BRICK SALES CO., a Michigan corporation, CITY ELECTRIC SUPPLY COMPANY, a Massachusetts corporation, CONSTRUCTION AHEAD, INC., an Illinois corporation, D &V EXCAVATING, a Michigan corporation, E.L. PAINTING CO., a Michigan corporation, E.L.S. CONSTRUCTION, INC., a Michigan corporation, EVERGREEN CIVIL, LLC, a Michigan corporation, GAYLOR ELECTRIC INC., a foreign corporation, HARNISH FIREPROOFING, LLC, a Michigan corporation, JACKIE'S TRANSPORT, INC., a Michigan corporation, JERMOR PLUMBING & HEATING, INC., a Michigan corporation, JSC CONSTRUCTION, INC., a Michigan corporation, MASONRY DEVELOPERS, INC., a Michigan corporation, MICHIGAN WOODWORK, LLC, a Michigan corporation, QUANDEL CONSTRUCTION GROUP, INC., a Pennsylvania corporation, R.A.M. CONSTRUCTION SERVICES OF MICHIGAN, INC., a Michigan Corporation, SHARON'S HEATING & AIR CONDITIONING, INC., a Michigan corporation, STETSON BUILDING PRODUCTS, an Iowa Corporation, SUMMIT BUILDING SERVICES, LLC, A Michigan corporation, WELLING INC., an Ohio corporation, ZEELAND LUMBER AND SUPPLY CO., a Michigan

corporation and John Does 1-100,

Additional Lien Claimant Defendants,

And any and all Counter-, Cross-, and Third-Party Claims.

J. Benjamin Dolan (P47839)
James B. Cunningham (P63131)
Ariana F. Pellegrino (P79104)
Dickinson Wright, PLLC
Attorneys for Plaintiff
2600 W. Big Beaver Road, Suite 300
Troy, MI 48084
(248) 433-7200
bdolan@dickinsonwright.com
jcunningham@dickinsonwright.com
apellegrino@dickinsonwright.com

James A. Fink (P40386)
Joshua R. Fink (P66210)
Fink & Fink, PLLC
Attorneys for Receiver
320 North Main Street, Suite 300
Ann Arbor, MI 48104
(734) 994-1077
james.fink@finkandfink.com
joshua.fink@finkandfink.com

Ralph Colasuonno (P55019)
Warner Norcross & Judd, LLP
Co-Counsel for Receiver
45000 River Ridge Drive, Suite 300
Clinton Township, MI 48038
(248) 784-5033
rcolasuonno@wnj.com

Angela L. Jackson (P53930)
Bruce T. Wallace (P24148)
Adam M. Linkner (P78784)
Oscar A. Rodriguez (P73413)
Hooper Hathaway, PC
Attorneys for Defendant
126 South Main Street
Ann Arbor, MI 48104
ajackson@hooperhathaway.com
bwallace@hooperhathaway.com
alinkner@hooperhathaway.com
orod@hooperhathaway.com

John M. Sier (P39336)
Yasir Muhammad (P79976)
Kitch Drutchas Wagner
Valitutti & Sherbrook
Attorneys for Defendant
One Woodward Ave., Suite 2400
Detroit, MI 48226
(313) 965-2915
john.sier@kitch.com
yasir.muhammad@kitch.com

Ronald A. Deneweth (P27680)
Matthew C. Herstein (P68596)
Deneweth, Dugan & Parfitt, PC
Attorneys for Defendants Jermor
Plumbing & Heating, Inc. and
Harnish Fireproofing, LLC
1175 W. Long Lake Road, Suite 202
Troy, MI 48098-4437
(248) 290-0400
rdeneweth@ddp-law.com
mherstein@ddp-law.com

Marty A. Burnstein (P11443)
Law Office of Marty A. Burnstein
Attorney for Defendants ELS Construction,
Evergreen Civil, LLC and Jackie's
Transport, Inc.
1175 W. Long Lake Road, Suite 202
Troy, MI 48098
(248) 290-0400
mburnstein@martyburnsteinlaw.com

Roy C. Sgroi (P28168) Sgroi Law Firm, PLC Attorneys for Defendant Welling, Inc. 12845 Farmington Road, Suite 1 Livonia, MI 48150 (734) 421-9200 rcs@sgroilaw.com

Jeffrey G. Muth (P65041)
Christopher E. Nyenhuis (P80028)
Miller Johnson
Attorneys for Defendant Zeeland Lumber
and Supply Co.
45 Ottawa Avenue SW, Suite 1100
Grand Rapids, MI 49503
(616) 831-1700
muthjg@millerjohnson.com
nyenhuisc@millerjohnson.com

Gerald J. Richter (P38822)
Facca, Richter & Pregler, PC
Attorneys for Stetson Building Products, Inc.
6050 Livernois
Troy, MI 48098
(248) 813-9900
grichter@frplaw.com

R. Edward Boucher (P57251)
Kotz, Sangster, Wysocki, PC
Attorneys for R.A.M. Construction
Services of Michigan, Inc.
400 Renaissance Center, Suite 3400
Detroit, MI 48243
(313) 259-8300

James R. Case (P31583)
Michael D. Carroll (P53815)
Kerr, Russell & Weber, PLC
Attorneys for Defendant
Gaylor Electric, Inc.
500 Woodward Ave., Suite 2500
Detroit, MI 48226
(313) 961-0200
jcase@kerr-russell.com
mcarroll@kerr-russell.com

Eric J. Flessland (P35668) Butzel Long Attorneys for Defendant Amthor Steel 150 W. Jefferson, Suite 100 Detroit, MI 48226 (313) 225-7000 flessland@butzel.com

Bruce N. Elliott (P28770)
Conlin, McKenney & Philbrick, PC
Co-Counsel for Defendant Quandel
Construction Group, Inc.
350 S. Main Street, Suite 400
Ann Arbor, MI 48104
(734) 761-9000
elliott@cmplaw.com

Evan M. Chall (P72058) Wright Beamer, PC Attorneys for Sharon's Heating & Air Conditioning, Inc. 31500 Northwestern Hwy., Suite 140 Farmington Hills, MI 48334-2568 (248) 893-1407 echall@wrightbeamer.com

James L. Dyer (P32544)
Johnson, Rosati, Schultz
& Joppich, PC
Attorney for Defendant Summit
Building Services, LLC
822 Centennial Way, Suite270
Lansing, MI 48917
(517) 886-3800 jdyer@jrsjlaw.com

Andrew J. Natale (Ohio 0042110)
Thomas E. Cardone (Ohio0090270)
Frantz Ward, LLP
Attorneys for Quandel Construction Group
200 Public Square, Suite 3000
Cleveland, OH 44144
(215) 515-1660
anatale@frantzward.com
tcardone@frantzward.com

John R. Badeen (P71014) Xuereb Law Group, PC Attorneys for E.L. Painting Co. 7752 N. Canton Center Rd. Suite 110 Canton, MI 48187 (734) 455-2000 jbadeen@xuereblawgroup.com

John F. Fleming (P43323)
Kallas & Henk, PC
Attorneys for Assemblers Precast & Steel Services, Inc.
43902 Woodward Ave., Suite 200
Bloomfield Hills, MI 48302
(248) 335-5450 ext. 213
jfleming@kallashenk.com

Aaron W. Goren (P14203) Gottlieb & Goren, PC Attorneys for D&V Excavating, Inc. 30150 Telegraph Road, Suite 249 Bingham Farms, MI 48025 (248) 593-0090 agoren@g2law.net

Timothy J. Kramer (P36223)
Abbott Nicholson, PC
Attorneys for Construction Ahead, Inc.
300 River Place, Suite 3000
Detroit, MI 48207-4225
(313) 566-2500
tjkramer@abbottnicholson.com

I. Matthew Miller (P51351) Swistak Levine, PC Co-Counsel for Defendant Packard Square, LLC 30833 Northwestern Hwy. #120 Farmington Hills, MI 48334 (248) 851-8000 mmiller@swistaklevine.com

RECEIVER'S NOTICE OF FILING OF RECEIVER'S REPORT DATED AUGUST 25, 2017

TO: ALL COUNSEL OF RECORD

PLEASE TAKE NOTICE THAT THE ATTACHED RECEIVER'S REPORT DATED AUGUST 25, 2017 WILL BE FILED WITH THE COURT ON FRIDAY, AUGUST 25, 2017.

Respectfully submitted,

Dated: August 25, 2017

James A. Fink

Attorney for Receiver

Prepared by:

Fink & Fink, PLLC James A. Fink (P40386) Attorneys for Receiver

NOTICE OF FILING RECEIVER'S REPORT

The Receiver, McKinley, Inc., hereby files this Receiver's Report, dated August 25, 2017, in accordance with the Order Appointing Receiver entered on November 1st, 2016.

Respectfully submitted,

Matthew D. Mason, as

Representative for McKinley, Inc. receiver

for Packard Square LLC

320 N. Main Street, Suite 200

Ann Arbor, MI 48104 Phone: (734) 274-6300



Management Activity

During the timeframe from July 27th, 2017, though August 25th, 2017, McKinley, in its capacity as Receiver, performed the following tasks and made the following findings:

- JSC installed the roof on the pool house.
- Starky's continued the installation of the exterior framing in the drive through areas.
- Evergreen Civil started the off-site sanitary installation and completed the installation of the underground sanitary service line. Restoration of the hardscaping and landscaping will follow as well as final city approval.
- Hopp Electric continued its rough electrical work in the building as well as underground conduit work in the interior courtyard.
- Construction Ahead continued the installation of the fiber cement panels, including installation of the balcony and parapet details. In addition, Construction Ahead started the installation of vinyl siding in the interior courtyard, which is now approximately 75% complete.
- JSC continued work on exterior flashing and continued installation of roof curbs.
- Jermor Plumbing continued rough plumbing throughout the building, including in the pool house. Jermor had rough inspections on the second and third floors on the North side of the building.
- Sharon's continued rough HVAC work in apartments.
- The low voltage communications work continued within the apartment units.
- Thermal and sound insulation continued on the first and fourth floors.
- Fire suppression rough work was completed in the majority of the building, with the exception of the parking garage and North retail wing.
- Work began on the Packard Street approaches.
- Albanelli continued concrete installation throughout the site, including walkways adjacent to the building, pool courtyard patios, and sidewalk areas below the drive through areas.
- Golich began installing the storefront windows.
- RAM construction completed waterproofing repairs at the stair towers.
- Turner Landscaping installed plantings on the South side of the building.



- The model unit was completed though painting, including trim carpentry, and ceramic tile installation.
- Jalan continues to drywall units on the fourth floor in the North section of the building.
- McKinley had numerous meetings with O'Brien Construction to discuss the various aspects of the project.
- McKinley and O'Brien Construction held various meetings with subcontractors as the project continues to progress.
- McKinley continues to perform detailed, weekly site inspections of the entire project, in addition to its many other walks throughout the property.
- Receiver reviewed and prepared litigation filings and attended associated court hearings.

Exhibit List

Exhibit A - Site Photos

Exhibit B – General Ledger

Exhibit C - Bank Reconciliation

Exhibit D - Status Update on List of Issues and Defects

Exhibit E - Electrical Issues



Exhibit A



Vinyl siding installation and pool house roof installed.



Off-site sanitary installation.





Off-site sanitary installation.



Off-site sanitary installation.





Packard Street approach installation in process.



Packard Street approach installation in process.





Installation of the exterior framing and cement in the drive through areas.



Installation of the exterior framing and cement in the drive through areas.





Fiber cement siding installation.



Landscaping installation.





Insulation and drywall installation on the fourth floor.



Model unit cabinet installation.





Model unit trim carpentry and paint.



Model unit tile installation.

Site Job Id Code Dept Description
Balance Forward
HQ A/P Cash Disbursed for checks
10073-10074 HQ Wire out to Liberty Title Final easement development maintenance
agreement. AVP Cash Disbursed for checks 1075-10086
HQ 7/17 Funding HQ A/P Cash Disbursed for checks 10/087-10/087
HQ Wire to Liberty Title HQ 7/17 Funding
** Account Totals
Intercompany Accounts Receivabl Balance Forward
HQ Cash Intercompany Entry for 211920 HQ Cash Intercompany Entry for 211920 HQ Cash Intercompany Entry for 211920 Cash Intercompany Entry for 211920 HQ Cash Intercompany Entry for 211920 HQ Cash Intercompany Entry for 211920
** Account Totals
Other Accounts Receivable Balance Forward
Construction Supervision Fee Balance Forward
HQ MCKIINC - 4/17 Construction Supervision Fee 042017/211920 - 4/17 Consti

Database: ENTITY:		MCKINLEY 211920			General Ledger McKinley Associates		Page: Date: 8/1/2	2 8/1/2017
RCV GENLEDG	NLEDG				Packard Square			MA C
Cash					71/17 - 07/17			
Account Entity	Period	Entry Date	Src Reference	Site Job ce Id Code	Dept Description	Debit Credit	Balance	псе
1508-000 -	Construc	ction Super	1508-000 - Construction Supervision Fee (Continued)	Continued)				1
					** Account Totals	4,112.32 0.00	26,031.58	.58
1590-000		Con	Construction in Progress	rogress	Balance Forward		3,615,941.60	09
211920	07/17	7/3/2017	AP 631750	50 HQ	OBRICON - App#2 Job 1680	571,242.31	4,187,183.91	16.
211920	07/17	7/3/2017	AP 631750	OH OS	App #2 Job#1080 - App#2 Job #1680 DETEDIS - Relocation of of streetlights/streetlight posts at 2502 Packard	4,334.28	4,191,518.19	1.19
211920	07/17	7/3/2017	DL 927785	SS HQ	Vire out to Liberty Title Final easement development maintenance	250,000.00	4,441,518.19	19
211920	07/17	7/5/2017	AP 632280	30 HQ	agreentent. RAMCONS - Hard Cost Phase 1 - Prev Change Order	39,500.00	4,481,018.19	.19
211920	07/17	7/5/2017	AP 632280	80 HQ	RAMO1/211920 - RAMCONS - Hard Cost Phase 1 - Settlement Agreement	27,355.00	4,508,373.19	19
211920	07/17	7/5/2017	AP 632280	00 HQ	JOHTAG - Construction in progress	7,086.73	4,515,459.92	:92
211920	07/17	7/13/2017	. AP 633909	9 HQ	EVITATION - Construction in Progress	5,401.94	4,520,861.86	.86
211920	07/17	7/13/2017	. DL 939678	'8 HQ	Wire to Liberty Title	33,206.05	4,554,067.91	.91
						Subtotal: 938,126.31 0.00	938,126.31	3
					** Account Totals	938,126.31 0.00	4,554,067.91	91
3105-000		Own	er Contributic	Owner Contribution (Current Year)	Balance Forward		-5,583,278.96	96
211920 211920	07/17	7/12/2017 7/31/2017	DL 933205	15 HQ 19 HQ	7/17 Funding 7/17 Funding	38,607.99 2,665,313.22	-5,621,886.95 -8,287,200.17	.95
						Subtotal: 0.00 2,703,921.21	-2,703,921.21	21
	7.0				** Account Totals	0.00 2,703,921.21	-8,287,200.17	.17
3165-000		Reta	Retained Earnings	S.	Balance Forward		-586,624.52	.52

Database: MCP ENTITY: 2118 RCV_GENLEDG Cash	e: MCKINL 211920 ENLEDG	MCKINLEY 211920 DG					General Ledger McKinley Associates Packard Square 07/17 - 07/17			Page: Date: Time:	3 8/1/2017 01:50 PM
Account	Period	Entry	Sound of Carry	Site	Job				Debit	Credit	Balance
000				1		nebi					
2030-000		Adve	Advertising				Balance Forward				0.00
211920	07/17	7/5/2017	AP 632280	OH O	~		APAGUI - November 2016-advertising		764.10		764.10
211920	07/17	7/13/2017	DL 939678	8 HO	~		10-327 10-40 - Cust Na. V8035Q ZILREN - Advertising		250.00		1,014.10
211920	07/17	7/13/2017	DL 939678	8 HQ	~		113 00 12 1534 FORMEDI - 9/30/16 - 9/30/16 Advertising INDODES 110		635.00		1,649.10
211920	07/17	7/13/2017	DL 939678	8 HQ	~		FORMEDI - 10/1/16 - 10/31/16 Advertising		635.00		2,284.10
211920	07/17	7/13/2017	DL 939678	8 HQ	~		FORMED - 11/1/16 - 11/30/16 Advertising		635.00		2,919.10
211920	07/17	7/13/2017	DL 939678	g 9	~		N0001/29921 MOREDI - 12/1/16 - 12/31/16 Advertising		635.00		3,554.10
211920	07/17	7/13/2017	DL 939678	8 H	~		IN0007 / 17283 FORMEDI - 1/1/17 - 1/31/17 Advertising IN000745429		635.00		4,189.10
								Subtotal:	4,189.10	0.00	4,189.10
						#	** Account Totals	4,1	4,189.10	0.00	4,189.10
5065-000		Medi	Media Advertising				Balance Forward				0.00
211920	07/17	7/5/2017	AP 632280	DH C			ZILREN - Advertising Packard Square		250.00		250.00
211920	07/17	7/13/2017	DL 939678	S H	~		Reclass- Advertising			250.00	0.00
								Subtotal:	250.00	250.00	0.00
						**	** Account Totals	(4)	250.00	250.00	0.00
2090-000		Mark	Marketing PR				Balance Forward				3,175.00
211920	07/17	7/13/2017	DL 939678	ğ H	٠.		Reclass Advertising			3,175.00	00.00
								Subtotal:	0.00	3,175.00	-3,175.00
						*	** Account Totals		0.00	3,175.00	0.00
5305-000		Legal	_				Balance Forward			1,0	1,049,673.41

Database: ENTITY:		MCKINLEY 211920				Mck	General Ledger McKinley Associates		Pa	Page:	4
RCV_GENLEDG	NLEDG					Δ.	Packard Square		Ţ		01:50 PM
Cash							07/17 - 07/17				
Account		Entry		Site	dol						
Entity	Period	Date	Src Reference	e (q		Dept Description		Debit	Credit	ä	Balance
5305-000 - Legal (Continued)	Legal (C	ontinued)									
211920	07/17	7/5/2017	AP 632280	DH C		REACRAN - P.	- Packard Square Legal Fees -	3,011.00		1,052,684.41	184.41
211920	07/17	7/5/2017	AP 632280	O HQ		~ <u>~</u>	- Packard Square Ann Arbor Mi - Legal Fees Packard Square	13,083.00		1,065,767.41	67.41
211920	07/17	7/5/2017	AP 632280	Ö HÖ			- Matter #150929.171796 - Legal Fees Packard Square -	937.00		1,066,704.41	04.41
211920	07/17	7/13/2017	7 DL 939678	8 A		egal	- Matter #150929.171783	21,426.20		1,088,130.61	30.61
								Subtotal: 38,457.20	0.00	38,4	38,457.20
						** Account Totals		38,457.20	0.00	1,088,130.61	30.61
5320-000		Profe	Professional Services	seo		Balance Forward	Į2,				0.00
5325-000		Cons	Consultation			Balance Forward	<i>p</i> ,			42,3	42,386.62
211920	07/17	7/5/2017	AP 632280	OH (GET& - Lega	- Legal - Canyon/Packard	21,426.20		63,8	63,812.82
211920	07/17	7/13/2017	, DL 939678	E HQ		GET& - Legal			21,426.20	42,3	42,386.62
								Subtotal: 21,426.20	21,426.20		0.00
						** Account Totals		21,426.20	21,426.20	42,3	42,386.62
2200-000		Elect	Electricity			Balance Forward	p.				00:00
5775-000		Signs	s			Balance Forward	ą				00.00
2905-000		Real	Real Estate Taxes			Balance Forward	ď				0.00
5950-000		Insul	Insurance			Balance Forward	ď				0.00
211920	07/17	7/3/2017	DL 927785 AP 632280	O O		Reclass- Commitm FIRAME - Comm 2017 2182-2182109445	Reclass- Commitment Update 4/17-5/17 FIRAME - Commitment Update April-May 2017 2182-2182109445 -	350.00	350.00	Υ	0.00

RCV GENLEDG					Time:	01:50 PM
			07/17 - 07/17			
Account Entry Entity Period Date	Src Reference	Site Job Id Code	Dept Description	Debit	it Credit	Balance
5950-000 - Insurance (Continued)	tinued)					
				Subtotal: 350.00	0 350.00	0.00
			** Account Totals	350.00	350.00	00.00
6100-000 N	Management Fees-McKinley	lcKinley	Balance Forward			75,000.00
211920 07/17 7/5/2017	117 AP 632280	М	MCKIINC - 211920_000000001 - Management Fee	15,000.00	C	90,000.00
				Subtotal: 15,000.00	00.00	15,000.00
			** Account Totals	15,000.00	0.00	90,000.00
6200-000 P	Payroll		Balance Forward			23,945.00
211920 07/17 7/5/2017	117 AP 632280	오	MCKCOM1 - 4/1/17 - 4/30/17 CPM04302017CA - Dept 507 - Chris Allen - CPM	6,300.00	0	30,245.00
				Subtotal: 6,300.00	0.00	6,300.00
			** Account Totals	6,300.00	0.00	30,245.00
6371-000 B	Building Office Rent		Balance Forward			0.00
6372-000 S	Storage		Balance Forward			22,004.66
6520-000 W	Water & Sewer		Balance Forward			1,294.15
6615-000 G	Guard Service Contract	act	Balance Forward			82,016.70
211920 07/17 7/5/2017	17 AP 632280	ΣŦ	PRUDSEC - Security 1/27/17-2/2/17	3,311.00	0	85,327.70
211920 07/17 7/5/2017	17 AP 632280	언	S64870.17 PRUDSEC - Security 2/3/17-2/9/17	3,530.00	0	88,857.70
211920 07/17 7/5/2017	17 AP 632280	Ä	388233.17 PRUDSEC - Security 2/10/17-2/16/17	3,867.63		92,725.33
211920 07/17 7/5/2017	17 AP 632280	욧	388330.17 PRUDSEC - Security 2/17/17-2/23/17	3,311.00		96,036.33
211920 07/17 7/5/2017	17 AP 632280	Я	900022.17 PRUDSEC - Security 3/3/17-3/9/17	3,311.00		99,347.33

Database: MCK ENTITY: 2119 RCV GENLEDG	MCKINLEY 211920 DG						General Ledger McKinley Associates Packard Square		Page: Date: Time:	6 8/1/2017 01:50 PM
							07/17 - 07/17			
Period	Entry Date	SrcReference	0,	site Job Id Code	e Dept	ot Description		Debit	Credit	Balance
	ervice Cont	6615-000 - Guard Service Contract (Continued)	(par							
	7/5/2017	AP 632280	ØH 00	a		PRUDSEC	- Security 3/10/17-3/16/17	3,457.00		102,804,33
	7/5/2017	AP 632280	M HQ	ø		389694.17 PRUDSEC	- - Security 3/17/17-3/23/17	3,311.00		106.115.33
	7/5/2017	AP 632280	M HQ	ø		PRUDSEC	- - Security 4/28/17-5/4/17	3,311.00		109.426.33
	7/5/2017	AP 632280	0 HQ	Ø		391714,17 PRUDSEC	- - Security 5/12/17-5/18/17	3,530.00		112,956.33
	7/5/2017	AP 632280	OH O	ø		392287.17 PRUDSEC - Si 5/19/17-5/25/17	- - Security service 25/17	3,311.00	·	116,267.33
	7/5/2017	AP 632280	O HO	ø		392573.17 PRUDSEC	- - Security 5/26/17-6/1/17	3,530.00	·	119,797.33
	7/5/2017	AP 632280	O HQ	a		393139.17	- Security 6/3/17-6/8/17	3,311.00	·	123,108.33
								Subtotal: 41,091.63	0.00	41,091.63
					*	** Account Totals	sle	41,091.63	00.00	123,108.33
	Real	Real Estate Taxes				Balance Forward	iward			35,966,99
	Insul	Insurance				Balance Forward	nward			62,890.00
	7/3/2017	DL 927785	5 HQ	a		FIRAME - (FIRAME - Commitment Update 4/17-5/17	350.00		63,240.00
	7/5/2017	AP 632280	OH O	C		Z 102-Z 18Z 109445 SECUINS - Insur 877571059262 -	109445 - Insurance related charges 262 - Client: 8775703066	4,553.00		67,793.00
								Subtotal: 4,903.00	0.00	4,903.00
					‡	** Account Totals	ıls	4,903.00	0.00	67,793.00
					** Gran	** Grand Totals		4,543,925.48 4,543,925.48	925.48	

Packard Square Private Bank - Operating Account GL Account # 1101.000 Period Ending 7/31/2017

	Exhi	bit C		
Entity 211920		20op		
Ending balance from bank statement Add deposits in transit:	(-	Deposit Date	Amount	\$2,788,606.74
Total deposits in transit				\$0.00
Subtract outstanding checks:		Check Number See list	Amount	-
Adjusted bank balance	7/31/2017	**		\$2,788,606.74
Balance per Property G/L <u>Adjustments</u>				\$2,788,606.74
Adjusted Ending Balance per G/L	7/31/2017			\$2,788,606.74
Difference (Research any differences)				\$ -
			Prepared by: Date:	D. Leith 8/1/2017



120 South LaSalle Street, Chicago, IL 60603 ADDRESS SERVICE REQUESTED

MCKINLEY INC.

OPERATING ACCOUNT

320 N MAIN STREET STE 200

ANN ARBOR MI 48104-1127

RECEIVER FOR PACKARD SQUARE LLC

△ EWHOWEN

Last Statement: Statement Ending:

June 30, 2017 July 31, 2017

Total Days in Statement Period:

Page 1 of 5

31

Customer Service Information

For Personal Assistance, Call: 248-566-4793 STEVE ANDERSON



Visit Us Online: www.theprivatebank.com



Written Inquiries: The PrivateBank 34901 Woodward Avenue, Suite 200 Birmingham, MI 48009

BUSINESS CHECKING

Account Number: 0002417847

Balance Summary

Beginning Balance as of 06/30/17	\$ 1,224,921.99	
+ Deposits and Credits (2)	2,703,921.21	
 Withdrawals and Debits (18) 	1,140,236.46	
Ending Balance as of 07/31/17	\$ 2,788,606.74	
Average Balance	\$ 380,426.40	
Low Balance	\$ 123,293.52	
Enclosures	16	

Checks Posted

* Skip in check sequence

Number	Date	Amount	Number	Date	Amount
10051	07/07	91,231.90	10080	07/06	19,112,32
10073*	07/05	571,242.31	10081	07/10	41,091,63
10074	07/17	4,334.28	10082	07/13	66,855.00
10075	07/10	764.10	10083	07/06	3,011.00
10076	07/10	350.00	10084	07/10	4,553.00
10077	07/11	21,426.20	10085	07/11	14,020.00
10078	07/12	7,086.73	10086	07/10	250.00
10079	07/06	6,300.00	10087	07/18	5,401.94
			Item Count 16	Subtotal	\$857,030,41

Debits

Date	Description The state of the st	Subtractions
07/03	Term-outgoing Wt/Dom	250,000.00
	BNF LIBERTY TITLEAGENCY OBI CUSTOMER NAME: HARBOR DEV	•
	ELOPMENT, LLC PSDFILE NO. M110325	
07/13	Term-outgoing Wt/Dom	33,206.05
	BNF LIBERTY TITLEAGENCY OBI CUSTOMER NAME: HARBOR DEV	30,200.00
	ELOPMENT, LLC PSDFILE NO. M110325	



Statement Ending:

MCKINLEY INC. July 31, 2017 Page 2 of 5

BUSINESS CHECKING (continued)

Account Number: 0002417847

Credits

Date 07/11	Description Incoming Wire-dom	Additions 38.607.99
	ORG CAN IV PACKARD SQUARE LLC OBI RECEIVER FOR DRAW #0 9	00,007.00
07/31	Incoming Wire-dom ORG CAN IV PACKARDSQUARE LLC OBI DRAW #9 - PACKARD	2,665,313.22

Daily Balances

Date	Amount	Date	Amount	Date	Amount
06/30	1,224,921.99	07/07	284,024.46	07/13	133,029,74
07/03	974,921.99	07/10	237,015.73	07/17	128,695,46
07/05	403,679.68	07/11	240,177.52	07/18	123,293,52
07/06	375,256.36	07/12	233,090.79	07/31	2,788,606,74

Overdraft/Return Item Summary

Description	Total for this Period	Total Year to Date
Total Overdraft Fees	\$0.00	\$0.00
Total Returned Items	\$0.00	\$0.00



Statement Ending:

MCKINLEY INC. July 31, 2017 Page 3 of 5

McKiniey Inc., Receiver for Packard Sousre LLC 220 N Main Stress Ste 200 Ann Arton Mid Stoke	e Proveta Barol				pay
Oate 4/26/2017 Ninery One Thousand Two Hundred Thir	Check No. 010051 \$91,231.	.90	1. C. 24 (\$2.50g) (10)		ETG delane ruco Aut 22
Evergreen ONS LLC i 143 Cadyconine 63 II3 Northville, Mr. 48187	- areas	_	20170706009401860188		y iz the orek ti Huttington Ba '3- deposit only Swegreen Cold, LLC '91 382275918
"010051" (10710064A6): 241		v ve			n.
Check # 10051, Posted 07/07/17, Amou	nt 91,231.90		Check # 10051, Posted 07/07/17, Amount 91,23	31.90	
Michfolog No. The Michael Square LLC 320 M Main Street State 200 Ann Arton M 4104 M	Province States		Perty dates Diving Change Change Change Original Perty design	20 ± 20 E	15.0 (S. C.
Quie 6/39/2017 Five Hundred Bevenly One Thousand Two Hundred	Check No. 010073 \$571,242,3 d Forty Two AND 31/100 Collare	-	hand of housed and year to see the second of	E PRIVATE GARACTE	0'30,000 Card
O'Brise Construction Co., Inc. 956 Livernole Troy, MI 48083	- Mario		The second secon	1	2 0
ro 10073* 1507100548511 24171 Check # 10073, Posted 07/05/17, Amour			Obsel # 40070 Bash 4070507	10.01	111
Check # 10073, Posted 07/05/17, Amoun	10 57 1,242.31		Check # 10073, Posted 07/05/17, Amount 571,2	42.31	
Date 6/30/2017	Terral Bank 78 70 250 Telocation Check No. 010074 \$4,334.2:	8	Charge Land State College Coll	ACCIONAL DE	on and the
DYE Energy Company COOT feaquety Road Spile Ville, Mil 46111	P AND 28/100 Dollare		A 7 (v.) 1 (2 (v.) 1 (1 v.) 2 (v.) 2 (v.) 3 (v.) 4	THE STATE OF THE STATE OF	TX Oppose (In-
03007% #07100E486# 2417#			13: 13 11		34.91
Check # 10074, Posted 07/17/17, Amoun	t 4,334.28		Check # 10074, Posted 07/17/17, Amount 4,334	.28	
McKichley Inc. Resident for Pockaid Square LLC 320 M Main Blood Size 200 Ann Aibor MI 48104 Cale 7/5/2017	Check No.	1	The state of the s	DO DET NING CR PA LACE DANK	Indomercan T = 68
ReniPalh Holdings, Inc. Apariment Guide P.G. 80x 48044 Alland Apariment Guide P.G. 80x 4804 Alland Apariment Guide P.G. 80x 4804 Alland Apariment Guide P.G. 80x	010075 \$784,11		B & # 45 558	OUTSING HAND ON SCHEEDINGS IN SCHOOL STATES AND STATES PARTE BAD STD BANK OF AMERICA	172 ATL-402039
**O10075* *:071006486: 24178	£, 7±°		Be delicated and the second and the		
Check # 10075, Posted 07/10/17, Amoun	764.10		Check # 10075, Posted 07/10/17, Amount 764.10	0	
McKinsey Inc. Receiver for Psoliant Square LLG 200 H Mein Direct tile 200 Ann Articy M Africa Date 776/2017 Three Hundred Fifty AND 60/10 First American Till's Company PG 884 31001-3276 Pasademic CA 91110-2276	Chest IIII 900000 \$350.00	Hardwell	Proposition of the control of the co	(A LOST HERTE, TOURS OF SPORMED HERE	Activa Listinas
	Transcription		E. S.	i a	
heck # 10076, Posted 07/10/17, Amount		إلــ	Chack # 10076 Posted 07/10/17 Amount 250 00		1, 1, 1
THE THE PARTY OF T			Check # 10076, Posted 07/10/17, Amount 350.00		
McKiniey Inn. Heaties for Pakkard Square LLC 330 H Melai. Parkard Ste 200 Ann Arbor Mi 48104 Date 7/5/2017	Nate Sept. Check No. 010077 \$21,428.21	_	Services of the Control of the Contr		Ton team
7/6/2017 Twenty One Thousand Four Hundred Twenty		<u> </u>		- 1	100
Geller & Gomes P.C 2 Especiative Blind Ste 308 3uffern, NY 18601	a will	_4	marketing and a second and a se	A PART OF THE PART	¥5
heck # 10077, Posted 07/11/17, Amount		ــالـــ	hook # 10077 Pooled 07/44/47	200	# E
neck # 10077, Posted 07/11/17, Amount	Z1,420.2U	C	heck # 10077, Posted 07/11/17, Amount 21,426	5.20	



Check # 10083, Posted 07/06/17, Amount 3,011.00

Statement Ending:

MCKINLEY INC. July 31, 2017 Page 4 of 5

7			
Martintey ion. Receiver for Paulistal Square LLC 120 N Main Street Sta 200 Ann Arbor Mi 48104	The Private Street		Acres from Street Control of S
	Osta Check No. 7/5/2017 010078	\$7,088_73	
John Tagle Associates, Inc. 5485 Corporata Drive Sis 305 Troy, MI 48090	2 guisso		Assembly the second sec
#3 100 78#	107 LODG 486 6 24 L 78 L 78		The state of the s
Check # 10078, Posted	07/12/17, Amount 7,086.73		Check # 10078, Posted 07/12/17, Amount 7,086.73
Mukiniey Inc. Receiver for Packerel Square LLC 320 N Main Greet Ste 200 Ann Arbor MI 48104	The Private Gank		The state of the s
	Date Check No. 7/5/2017 010079 Thousand Three Hundred AND BN 109 Deltars	\$6,300.00	70170703010127304001(9)17
McKinley Companies, LLC 320 M. Main Birset Ann Assor, MI 48104	J-g-using		Project Francisco Francisc
	07/06/17, Amount 6,300.00		Check # 10079, Posted 07/06/17, Amount 6,300.00
			
McMinley Inc. Receiver for Paulaint Square LLC 338 N Main Street the 200 Ann Artior Mt 48104	Chairs Chross Feet. 775-2047 010000		Total Comments of the Comments
Nineteen	These and One Hundred Twelve AND 32/100 Dollers	\$19,112 32	7 F Fixed B P
McKinsey foo. ID #MCKING	10710061868 24170476		West State Flant and a property of the prope
	07/06/17, Amount 19,112.32		Check # 10080, Posted 07/06/17, Amount 19,112.32
			Theorem 10000, Posted 97/00/17, Ambuilt 19, 112,32
McKinky Ind. Pacoval to Pickert agues LLC 320 N Main Street Sia 200. Ann Astor MI 40104			Distribution and State S
Fariy	Oate Check No 7/8/2017 010081	\$41,091,63	The state of the s
Predesting Security Inc. 2069 Surake Read Sts. 400 TAYLOR, MI 48180	14月95		Common and and and an analysis of the state
	071006486# 2417847#		[[[1 1 1 1 1 1]
Lineck # 10081, Posted C	07/10/17, Amount 41,091.63		Check # 10081, Posted 07/10/17, Amount 41,091.63
Mickiniay Inc. Recisives for Penhard Square LLC 320 N Main Street 6to 200 Ann Arbor MI 48104	The ilfrients itsels		Seq: L Dept: U02221 Date: 07/12/17 Date: 07/12/17
Slxty Six Tr	7/5/2017 d10883 sousand Eight Hundred Fifty Five AND 00/100 Dollars	\$66,855.00	and the state of t
RAM COUNTY, SETTICES OF MI, Inc., RAM CONEY, SETVICES OF MI, Inc., 13800 Eckles Road Livonis, MI 48150	J-g-wildo		Contract of Michigan Inc. 1
010085	071006486C 2417847W		
Check # 10082, Posted 0	7/13/17, Amount 66,855.00	-	Check # 10082, Posted 07/13/17, Amount 66,855.00
McKinley Inc. Receiver for Psckard Square LLC 329 N Main Street Site 200 Arin Arbor MI 48104	The Private Base		County towns on the County towns of the County towns on the County town on t
	Date Check No. 3/4/2017 010003	\$3,011.00_	Control of the contro
Journal Main Ser. Burn 3-52 Ann Arbor, MI 48504	J. J. was		Bank of Ann Arbor >072413735< FINK AND VAJVO 0057613621 2017-07-05
/010083F #0	7710054860 2417847P		0057613821 2017-07-05

Check # 10083, Posted 07/06/17, Amount 3,011.00



Statement Ending:

MCKINLEY INC. July 31, 2017 Page 5 of 5

Merch USA, Inc. P.O. IODS 64 ** *CC 7 LODS 44 ** CC 7 LODS 44	December 2002-150 10
	-2 -3
Check # 10084, Posted 07/10/17, Amount 4,553.00 Check	# 10084, Posted 07/10/17, Amount 4,553.00
Meckfinish fire. Heriniyer for Pankard Square LLC The Prince Sank	Congar



Check # 10085, Posted 07/11/17, Amount 14,020.00





Check # 10086, Posted 07/10/17, Amount 250.00

Check # 10086, Posted 07/10/17, Amount 250.00



Check # 10087, Posted 07/18/17, Amount 5,401.94

Check # 10087, Posted 07/18/17, Amount 5,401.94

Database: MCKINLEY Outstanding Check List for Banks Page: 1 Report Id: MRI_OUTLST McKinley Associates Date: 8/2/2017 Outstanding Checks as of 7/31/2017 Time: 09:50 AM Bank Account 920op The Private Bank Check Check Vendor Check # Date Period Number Vendor Name Amount

Outstanding Check Total:

0.00

Exhibit D

Packard Square - List of Issues and Defects Encountered to Date

- 1. There were OSHA safety issues throughout the property upon takeover (11/1/2016). [Update] Installed guard rails throughout the property. Installed fire extinguishers throughout the property.
- 2. There was a lack of waterproofing throughout the property. [Update] Added coping where is was missing in large portions of the building.
- 3. The entire site was a mess; a massive cleanup of debris was required using multiple 40 yard roll off dumpsters. [Update] Crews went through the site and picked up debris. Overall, eight, thirty cubic yard roll off dumpsters of rubbish were removed.
- 4. No expansion joints were installed in the siding. The siding manufacturer explicitly said that expansion joints are necessary for this project. In addition, the building is not yet even loaded with the additional materials for the next phases of construction, which will cause building settling. [Update] Construction Ahead is back on site making necessary repairs.
- 5. There were multiple improper sequencing and delivery issues throughout the project. [Update] The materials that were delivered prematurely were organized and store in better conditions. All sensitive materials are now being stored in the garage.
- 6. The site was not positioned to be able to do work during the winter. [Update] The site was winterized, including installing the drive lane.
- 7. There was no concrete slab in the lower level parking garage. [Update] The concrete slab was poured.
- 8. Window limiters were not installed. These are required to meet code. [Update] The window limiters have been identified and will be installed in proper sequence.
- Many building materials were delivered and/or ordered out of sequence (screens, doors, cabinets, countertops, sinks, etc.), causing additional storage and labor costs. – [Update] This continues to be true. On site materials have been organized so they may be used in the most productive manner.
- 10. Unorganized finished materials were strewn throughout the site. [Update] To the extent possible, on site materials have been more properly staged so they may be used in the most productive manner.
- 11. The courtyard was prematurely built in/enclosed out of sequence before all major work was completed. As a result, larger machines are not able to access the courtyard in order to complete major necessary work. Additional shoring was required in order to bring in smaller machinery. [Update] Shoring was installed which allowed small machinery to access the courtyard. The shoring will remain in place until all major construction is completed within the courtyard.

- 12. Drainage was not installed in the courtyard, further exasperating the difficulty of working in the confined area. -[Update] Drainage was installed in the courtyard.
- 13. Roof coping was not installed throughout the property, resulting in water penetration. [Update] Roof coping was installed to the extent possible throughout the site. The balance of the parapet has been weatherized.
- 14. There was improper flashing behind the wall system, at the wall and roof intersection, allowing for water penetration. [Update] Fiber cement siding was removed at these locations in order to install proper flashing at wall and roof intersections.
- 15. The footings were initially poured at an insufficient depth. This resulted in the building shifting and the need for helical pier installation. It was noted that one of the helical piers was not installed. The building's prior shifting has necessitated the ongoing monitoring of the building and additional testing. [Update] Structural monitoring was completed and the missing helical pier was installed.
- 16. The wrong mastic was used in an attempt to fix the sloping flooring above the retail wings. By 11/1/2016, this material was already crumbling. [Update] This repair will be made in proper sequence when the lightweight concrete topping slap is poured.
- 17. The area where the vapor barrier system was installed was left exposed to the elements. [Update] The vapor barrier system was repaired under the supervision of AKT Peerless, including the installation of the concrete subgrade (compacted and tested by 3rd party engineers) and the concrete slab was installed, also under the supervision of AKT Peerless.
- 18. There were a few areas where the existing fencing was compromised so more substantial fencing was ordered to properly secure the site. The entire site was not secure. [Update] Fencing remains secure throughout the site.
- 19. No temporary doors were installed for winter. [Update] Temporary doors were installed throughout the site.
- 20. Fire dampers were not installed nor included in the building plans. [Update] Fire dampers were ordered and the installation is in progress.
- 21. There are large shafts in each unit that still need to be fire rated. However, many of these shafts have been dry walled around out of sequence, thus preventing access in order to complete necessary fire rating. [Update] The disassembly that is required is currently in progress by the carpenters as well as the completion of the drywall as scheduled. This work is being completed under close municipal supervision.
- 22. Cabinets and countertops were fabricated without first measuring the actual framing in each unit. There are concerns about the cabinets fitting properly. [Update] Walls were re-framed/relocated, re-installed as required to accommodate cabinet and counter per drawings. Counters are onsite.
- 23. The plumbing for toilets were located with vent stacks directly under trusses. The truss systems are therefore interrupting the vertical flow of plumbing stacks.

- [Update] Modifications are underway. Any truss modifications are being reviewed and approved by a professional engineer.
- 24. There is missing truss bracing and tie downs. Additional work was completed out of sequence so now there isn't easy access to add them which now requires additional work after the fact. [Update] All of the trusses have been braced and framing hardware installed in the North wing. The remaining areas will be addressed due time.
- 25. There are materials on site that do not match the site drawings and specifications, such as the shower pans. [Update] In order to be as efficient as possible, we are working with the materials on site which will be installed to manufacturer's specifications under the supervision of a professional architect.
- 26. There was a general lack of municipal inspections which necessitated starting over from the beginning with the city inspection process. [Update] We've met with the city multiple times and restarted the inspection process.
- 27. On the first day as Receiver, McKinley met with one of the building inspectors who said it had been months since he had been on site. [Update] We've met with the city multiple times and restarted the inspection process.
- 28. Fire services were installed but not inspected by the city. [Update] We've discussed the fire services with the city.
- 29. Domestic water and fire service lines were routed into areas that were not conditioned. [Update] We are working with both the city and a professional architect on the design of the water and fire services line entrance.
- 30. Modifications were necessary to the sanitary system in order to maintain ceiling height. [Update] The sanitary system in the garage area has been installed to achieve the highest ceiling height possible.
- 31. Improper gaskets were installed in the water service lines and need to be replaced. [Update] We've discussed the solution with the city and this modification will be made in due course.
- 32. No accommodations were considered for ventilation for future restaurant/commercial uses in the retail wings. [Update] We are working with a professional architect and engineer on a solution.
- 33. No elevator sump crocks or sump pumps were installed in the elevator pits. Further, these were removed from the site plans. [Update] Elevator sump crocks were installed and sump pumps will be installed at appropriate time.
- 34. The swimming pool does not have the necessary tank that dilutes the chlorine before it goes into the main sewer lines as part of the draining process. [Update] We've made accommodations for the addition of the necessary equipment.
- 35. There are vertical cracks in the concrete walls in the lower level parking garage with water infiltration via the courtyard. [Update] We had the cracks inspected by an engineer. In addition, courtyard drainage was installed which alleviated the issue.

- 36. The roof was hastily and poorly installed with debris such as nails left underneath the membrane. [Update] The roof contractor is back on site making necessary repairs and maintain the manufacturer's warranty.
- 37. The majority of the plumbing in the lower level parking garage was crushed and needed to be replaced. [Update] All of the plumbing repairs were completed.
- 38. There are electrical feeders that cross through rated fire assemblies throughout the building. [Update] We are working with a professional architect and the city on the correction.
- 39. The RC channel was installed upside down throughout the building. [Update] We are working with the city on the issue.
- 40. Additional fire suppression is required in the stairwells and was red tagged by the inspector. [Update] The fire suppression subcontractor is back on site making all necessary repairs.
- 41. The building envelope is not complete. For instance, the paneling in the inner courtyard and balconies are not complete. [Update] The respective trades are back on site working to complete the building envelope.
- 42. There are numerous electrical issues throughout the building. An example of the issues encountered in one room are further listed in Exhibit E.
- 43. Foundation stem wall was mis-located and resulted in a 1.5" brick deviation, resulting in no brick ledge. [Update] A masonry material is planned for installation to correct the deficiently.
- 44. Garage door openings were framed three feet too narrow. [Update] Garage masonry openings are being enlarged to comply with revisions to plan.
- 45. The framing on the inner courtyard balconies is misaligned. It is believed to be an aesthetic issue and is being investigated further.
- 46. There is a framing issue in the front motorcade designed overhang causing misalignment of two symmetrical elements (the designed overhang and the columns) on the exterior of the front retail wings. [Update] The existing framing was modified to address the aesthetic challenge.
- 47. Multiple conflicts exist on the design of the HVAC servicing the corridors. Specifically, on the third and fourth floor corridors inadequate accommodations were made for both the sizing and coordination of the HVAC equipment and ductwork. [Update] The plan is to add an additional HVAC unit at the end of each hallway which will eliminate the equipment sizing issue and the coordination of the installation of the ductwork.
- 48. There are conflicts with the ductwork routing, as designed, and the existing door opening sizes and a lack of required soffits shown on the plans for accommodation of HVAC in the first floor common areas. The structural and architectural drawings conflict with the HVAC mechanical drawings.

^{*}We continue to discover new issues each week so this list is not exhaustive.

Exhibit E

Packard Square - Electrical Issues Encountered in Room 111

- 1. Microwave outlet is located in the wrong position.
- 2. Buried under cabinet wires are in the wrong location.
- 3. Over counter outlet is located behind the stove.
- 4. No island outlet over 6" to the counter.
- 5. Pinched wire above panel.
- 6. Kitchen outlet needs Fire Rated box.
- 7. There is no hot water heater disconnect.
- 8. There is no 3 way switch for living room.
- 9. Two wires in under cabinet light. Cannot be landed in specified under cabinet light fixture.
- 10. Vanity light not centered.
- 11. Vanity outlet not located above vanity.
- 12. The bath fan in the shower has no GFI protection.
- 13. Closet light is too close to the shelf.
- 14. There is no outlet in the hall.
- 15. The bedroom switch over the box fill.
- 16. A bedroom outlet is over 6'.
- 17. A bedroom outlet is over 12'.
- 18. There are wires directly on truss gusset in the bathroom.
- 19. Nail plates missing in many locations.
- 20. Living room ½ Switch over box fill.
- 21. Living room outlet over 12'.
- 22. There are 100+ staple violations which will not pass code.
- 23. Bedroom outlet over 6'.
- 24. Bath fan in shower no GFI protection.
- 25. Vanity outlet in mirror.
- 26. Vanity light not centered.
- 27. Bath switches neutral too short.
- 28. Bath switches no hot pigtail.
- 29. Bath light not centered.
- 30. Entry Switch box needed fiber box.

STATE OF MICHIGAN IN THE CIRCUIT COURT FOR THE COUNTY OF WASHTENAW

CAN IV PACKARD SQUARE, LLC, a Delaware limited liability company,

Plaintiff,

Case No. 16-990-CB Hon. Archie C. Brown

V

PACKARD SQUARE, LLC, A Michigan limited liability company, **PROOF OF SERVICE**

Defendant,

and

ALLIED BUILDING PRODUCTS CORP., an Ohio corporation, AMTHOR STEEL, a Pennsylvania corporation, ASSEMBLERS PRECAST & STEEL SERVICES, INC., a Michigan corporation, THE BELDEN BRICK SALES CO., a Michigan corporation, CITY ELECTRIC SUPPLY COMPANY, a Massachusetts corporation, CONSTRUCTION AHEAD, INC., an Illinois corporation, D &V EXCAVATING, a Michigan corporation, E.L. PAINTING CO., a Michigan corporation, E.L.S. CONSTRUCTION, INC., a Michigan corporation, EVERGREEN CIVIL, LLC, a Michigan corporation, GAYLOR ELECTRIC INC., a foreign corporation, HARNISH FIREPROOFING, LLC, a Michigan corporation, JACKIE'S TRANSPORT, INC., a Michigan corporation, JERMOR PLUMBING & HEATING, INC., a Michigan corporation, JSC CONSTRUCTION, INC., a Michigan corporation, MASONRY DEVELOPERS, INC., a Michigan corporation, MICHIGAN WOODWORK, LLC, a Michigan corporation, QUANDEL CONSTRUCTION GROUP, INC., a Pennsylvania corporation, R.A.M. CONSTRUCTION SERVICES OF MICHIGAN, INC., a Michigan Corporation, SHARON'S HEATING & AIR CONDITIONING, INC., a Michigan corporation, STETSON BUILDING PRODUCTS, an Iowa Corporation, SUMMIT BUILDING SERVICES, LLC, A Michigan corporation, WELLING INC., an Ohio corporation, ZEELAND LUMBER AND SUPPLY CO., a Michigan

corporation and John Does 1-100,

Additional Lien Claimant Defendants,

And any and all Counter-, Cross-, and Third-Party Claims.

J. Benjamin Dolan (P47839)
James B. Cunningham (P63131)
Ariana F. Pellegrino (P79104)
Dickinson Wright, PLLC
Attorneys for Plaintiff
2600 W. Big Beaver Road, Suite 300
Troy, MI 48084
(248) 433-7200
bdolan@dickinsonwright.com
jcunningham@dickinsonwright.com
apellegrino@dickinsonwright.com

James A. Fink (P40386)
Joshua R. Fink (P66210)
Fink & Fink, PLLC
Attorneys for Receiver
320 North Main Street, Suite 300
Ann Arbor, MI 48104
(734) 994-1077
james.fink@finkandfink.com
joshua.fink@finkandfink.com

Ralph Colasuonno (P55019)
Warner Norcross & Judd, LLP
Co-Counsel for Receiver
45000 River Ridge Drive, Suite 300
Clinton Township, MI 48038
(248) 784-5033
rcolasuonno@wnj.com

Angela L. Jackson (P53930)
Bruce T. Wallace (P24148)
Adam M. Linkner (P78784)
Oscar A. Rodriguez (P73413)
Hooper Hathaway, PC
Attorneys for Defendant
126 South Main Street
Ann Arbor, MI 48104
ajackson@hooperhathaway.com
bwallace@hooperhathaway.com
alinkner@hooperhathaway.com
orod@hooperhathaway.com

John M. Sier (P39336)
Yasir Muhammad (P79976)
Kitch Drutchas Wagner
Valitutti & Sherbrook
Attorneys for Defendant
One Woodward Ave., Suite 2400
Detroit, MI 48226
(313) 965-2915
john.sier@kitch.com
yasir.muhammad@kitch.com

Ronald A. Deneweth (P27680)
Matthew C. Herstein (P68596)
Deneweth, Dugan & Parfitt, PC
Attorneys for Defendants Jermor
Plumbing & Heating, Inc. and
Harnish Fireproofing, LLC
1175 W. Long Lake Road, Suite 202
Troy, MI 48098-4437
(248) 290-0400
rdeneweth@ddp-law.com
mherstein@ddp-law.com

Marty A. Burnstein (P11443)
Law Office of Marty A. Burnstein
Attorney for Defendants ELS Construction,
Evergreen Civil, LLC and Jackie's
Transport, Inc.
1175 W. Long Lake Road, Suite 202
Troy, MI 48098
(248) 290-0400
mburnstein@martyburnsteinlaw.com

Roy C. Sgroi (P28168) Sgroi Law Firm, PLC Attorneys for Defendant Welling, Inc. 12845 Farmington Road, Suite 1 Livonia, MI 48150 (734) 421-9200 rcs@sgroilaw.com

Jeffrey G. Muth (P65041)
Christopher E. Nyenhuis (P80028)
Miller Johnson
Attorneys for Defendant Zeeland Lumber
and Supply Co.
45 Ottawa Avenue SW, Suite 1100
Grand Rapids, MI 49503
(616) 831-1700
muthjg@millerjohnson.com
nyenhuisc@millerjohnson.com

Gerald J. Richter (P38822)
Facca, Richter & Pregler, PC
Attorneys for Stetson Building Products, Inc.
6050 Livernois
Troy, MI 48098
(248) 813-9900
grichter@frplaw.com

R. Edward Boucher (P57251) Kotz, Sangster, Wysocki, PC Attorneys for R.A.M. Construction Services of Michigan, Inc. 400 Renaissance Center, Suite 3400 Detroit, MI 48243 (313) 259-8300 James R. Case (P31583)
Michael D. Carroll (P53815)
Kerr, Russell & Weber, PLC
Attorneys for Defendant
Gaylor Electric, Inc.
500 Woodward Ave., Suite 2500
Detroit, MI 48226
(313) 961-0200
jcase@kerr-russell.com
mcarroll@kerr-russell.com

Eric J. Flessland (P35668)
Butzel Long
Attorneys for Defendant
Amthor Steel
150 W. Jefferson, Suite 100
Detroit, MI 48226
(313) 225-7000
flessland@butzel.com

Bruce N. Elliott (P28770)
Conlin, McKenney & Philbrick, PC
Co-Counsel for Defendant Quandel
Construction Group, Inc.
350 S. Main Street, Suite 400
Ann Arbor, MI 48104
(734) 761-9000
elliott@cmplaw.com

Evan M. Chall (P72058) Wright Beamer, PC Attorneys for Sharon's Heating & Air Conditioning, Inc. 31500 Northwestern Hwy., Suite 140 Farmington Hills, MI 48334-2568 (248) 893-1407 echall@wrightbeamer.com

James L. Dyer (P32544)
Johnson, Rosati, Schultz
& Joppich, PC
Attorney for Defendant Summit
Building Services, LLC
822 Centennial Way, Suite270
Lansing, MI 48917
(517) 886-3800 jdyer@jrsjlaw.com

Andrew J. Natale (Ohio 0042110)
Thomas E. Cardone (Ohio0090270)
Frantz Ward, LLP
Attorneys for Quandel Construction Group
200 Public Square, Suite 3000
Cleveland, OH 44144
(215) 515-1660
anatale@frantzward.com
tcardone@frantzward.com

John R. Badeen (P71014) Xuereb Law Group, PC Attorneys for E.L. Painting Co. 7752 N. Canton Center Rd. Suite 110 Canton, MI 48187 (734) 455-2000 jbadeen@xuereblawgroup.com

John F. Fleming (P43323)
Kallas & Henk, PC
Attorneys for Assemblers Precast & Steel Services, Inc.
43902 Woodward Ave., Suite 200
Bloomfield Hills, MI 48302
(248) 335-5450 ext. 213
jfleming@kallashenk.com

Aaron W. Goren (P14203) Gottlieb & Goren, PC Attorneys for D&V Excavating, Inc. 30150 Telegraph Road, Suite 249 Bingham Farms, MI 48025 (248) 593-0090 agoren@g2law.net

Timothy J. Kramer (P36223)
Abbott Nicholson, PC
Attorneys for Construction Ahead, Inc.
300 River Place, Suite 3000
Detroit, MI 48207-4225
(313) 566-2500
tjkramer@abbottnicholson.com

I. Matthew Miller (P51351) Swistak Levine, PC Co-Counsel for Defendant Packard Square, LLC 30833 Northwestern Hwy. #120 Farmington Hills, MI 48334 (248) 851-8000 mmiller@swistaklevine.com

PROOF OF SERVICE

On the date below I served via e-mail, Receiver's Notice of Filing of Receiver's Report Dated August 25, 2017 and this Proof of Service to all counsel of record.

I declare that the statements above are true to the best of my information, knowledge and belief.

Dated: August 25, 2017

Elizabeth M. Fenner

Prepared by:

Fink & Fink, PLLC James A. Fink (P40386) Attorneys for Receiver 320 North Main Street, Suite 300 Ann Arbor, MI 48104 (734) 994-1077