



Materials Recovery Facility
Safety Observation Form

Date: Thursday, June 30, 2016

Name of Observer: Shawn Qualls

Issues: See below.

Photos:





- No spill kit
- Emergency shut-off: cover not secured



Improper materials storage: crush hazard

Cylinder stored next to mountain of paper/cardboard [CGA P-1 1965, 3.3.6]





Left:

- Hot work taking place within ~35 feet of storage area for recyclable materials
- No burn permit posted



Right:

- Hot work prep in area where hot work shall not be permitted pursuant to MIOSHA Rule 1261(4)(d)
- No burn permit posted