



Materials Recovery Facility
Safety Observation Form

Date: Thursday, July 7th, 2016

Name of Observer: Shawn Qualls

Issues: See below.

Photos:



Transfer station gates broken




Top left: missing switch on conveyor

Top right: (Heads up) Panel hasn't been mounted yet, but when it is please make sure it is mounted such that the panel door is able to be opened/closed, proper working clearance is maintained, and that the unused holes on the front, sides and top of the enclosure are closed up.



Bottom: (Heads up) Need 30 in. of clearance at the top of stairs [1910.24(g)]. Currently 21 in. Control panel will need to be moved.



Top: Housekeeping –
aisleways/stairways need to be
kept clear.

Bottom: Employee wearing
baseball cap under hardhat; a few
others (not pictured) spotted with
ear buds in.



Looks like a part has come loose and is spinning freely. Just FYI.